



Fittings Checklist





Cross head and flat head screwdrivers also required for assembly


Parts Checklist 1 x1 3 x1 2 x1 6 x1 (5) x1 4 x1 (7) x1 9 x2 8 x1 10 x2 11 x215 x2 12 x1 13 x2 14) x2 16 x2 17) x2 18 x1


To prevent scratching:Lay the parts face down on a clean, flat, soft surface.
































##