



ax8




bx8




cx1



1




2




When assembling, ensure 2x slats per hole.

3



4



5

