




Suratto Bedside Table




Parts Checklist




① x2




② x2



③ x1




④ x1



⑤ x1


Fittings Checklist




① Cam Screw x4




② Cam Lock x 4



③ Screw x16




④ Sticker x16




Cross head Screwdriver also required for assembly

To prevent scratching:
Lay the parts face down on a clean, flat, soft surface.




1.




2.


Repeat on both sides.



3.




4.



5.

Repeat on both sides.



6.