


PO13218
T1 DITTO PINE



Parts Checklist



A X3



B X2

Fittings Checklist


①		X6
②		X6
③		X6
④		X1
⑤		X4

1




Repeat this step for both parts 2's


2



3



4



5

